



SERVICE BULLETIN # 00279

426 INDUSTRIAL BOULEVARD • KEARNEYSVILLE WV 25430-2776 • USA
Phone: (304) 728-7056 • Fax: (304) 725-6579 • Toll Free: (800) 931-9214

PAGE: 1 of 1

DATE: 9-26-06

REVISION: 00

SUBJECT: Incorrect Refrigerant Charge on Vender Serial Plate

of People
Required



MODELS: Australian RVV NG

Kit Number

Kit Description

356118

Refrigerant Charge Overlay Label Kit

TOOLS REQUIRED: None

ESTIMATED INSTALLATION TIME: <1 minute

REASON FOR BULLETIN: On the vender serial plates of some RVV NG's built for export to Australia, the refrigerant charge quantity is listed incorrectly. On these units, the charge is listed as "0.17 kg" instead of the correct charge, 0.23 kg.




The following areas of this vender contain voltage which can cause serious injury or even death: the main power cord, supplying 110 VAC to the evaporator, EMI filter, and refrigeration system; the power line from the EMI filter to the ballast and transformer; and the ballast, which can produce upwards of 600 volts. Remove power from vender before working in any of these areas.

INSTALLATION INSTRUCTIONS:

1. Thoroughly clean the serial plate to remove all dirt, oils, etc.
2. Place the replacement decal over the incorrect charge printed on the serial plate.

NOTE: There are two serial plates on the vender. One is located on the left-hand side of the door; the other is located on the kick plate of the vender's refrigeration unit. Check **BOTH** of these serial plates to ensure the correct charge is listed on them. The door serial plate is shown below.



Place replacement decal over the incorrect R134a charge listed on the serial plate.

In an effort to provide our customers with the latest information on our equipment, Royal Vendors sends service bulletins to customers using the original ship-to address or e-mail addresses, if supplied by our customers. We also post all service bulletins on our website at www.royalvendors.com. If for any reason a vender is moved to another location or is sold to another customer other than to whom Royal Vendors originally sent the machine, it is the responsibility of the original purchaser of the vender to notify the appropriate personnel of the service bulletin.

**ANY QUESTIONS??? CONTACT ROYAL VENDORS' CUSTOMER SERVICE DEPARTMENT
CALL TOLL FREE (800) 931-9214**