



SERVICE BULLETIN # 00019

201 INDUSTRIAL BOULEVARD • KEARNEYSVILLE, WV 25430

Phone: (304) 728-7056 • Fax: (304) 725-6579 • Toll Free: (800) 931-9214

PAGE: 1 of 1

DATE: 8-16-00

REVISION: 02

SUBJECT: Double or Dry Vending Problems

MODELS: 552-7,8 (Serial Numbers XXXX-1032, XXXX-1034 or XXXX-1051)

KIT NUMBER	KIT DESCRIPTION
058111	Spacer - (3 Deep)
058714	Wide Shim Right

BEFORE WORKING ON VENDER: Remove power from vender by unplugging vender's main power cord from the AC voltage power source (wall outlet).

Reason for Fix:

Because of holes punched in the column walls being out of tolerance (on subject serial numbers) some venders may experience "multiple" or "dry" vending.

Usage:

MULTIPLE VENDING:

For multiple vending caused by too much clearance in the rear of the column use part number 058,111,003 (This shim is a flat "spacer shim"). This shim should be added behind (against column wall) the current shim.

DRY VENDING:

For dry vending caused by not enough clearance in the rear of the column use part number 058,714,003 (This shim has a smaller "lower flange"). This shim should replace the current one, if any.

**ANY QUESTIONS??? CONTACT ROYAL VENDORS' CUSTOMER SERVICE DEPARTMENT
CALL TOLL FREE (800) 931-9214**