



SERVICE BULLETIN # 00260

426 INDUSTRIAL BOULEVARD • KEARNEYSVILLE WV 25430-2776 • USA
Phone: (304) 728-7056 • Fax: (304) 725-6579 • Toll Free: (800) 931-9214

PAGE: 1 of 1
DATE: 11-19-04
REVISION: 00


SUBJECT: Faulty Magnets in GIII Vend Chains

MODELS: GIII

REASON FOR BULLETIN: Some GIII vend chains produced for service parts were found in the field to have faulty magnets. **NOTE:** *This bulletin only concerns vend chains produced for service parts, not the original chains installed in the venders at the factory.*

HOW TO DETECT FAULTY MAGNETS:

1. Obtain a known good chain (such as a broken chain being replaced in which the magnets are known to be good).
2. Touch one of the magnets on the chain with the known good magnets to each of the magnets on the new chain. If the magnets on the new chain repel the magnets on the old chain, the new chain is good. If they stick together, the new chain is bad.



Magnet
Two of the four actuators ("rabbits") on the chain will have magnets.

Touch the magnets on the chains together. If they repel one another, the new chain is good. Make sure to check both magnets on the new chain.



In an effort to provide our customers with the latest information on our equipment, Royal Vendors sends service bulletins to customers using the original ship-to address or e-mail addresses, if supplied by our customers. We also post all service bulletins on our website at www.royalvendors.com. If for any reason a vender is moved to another location or is sold to another customer other than to whom Royal Vendors originally sent the machine, it is the responsibility of the original purchaser of the vender to notify the appropriate personnel of the service bulletin.

**ANY QUESTIONS??? CONTACT ROYAL VENDORS' CUSTOMER SERVICE DEPARTMENT
CALL TOLL FREE (800) 931-9214**