



SERVICE BULLETIN # 00166

201 INDUSTRIAL BOULEVARD • KEARNEYSVILLE, WV 25430

Phone: (304) 728-7056 • Fax: (304) 725-6579 • Toll Free: (800) 931-9214

PAGE: 1 of 1

DATE: 8-21-00

REVISION: 01

SUBJECT: GIII Loading Decal Discrepancy

MODELS: GIII Venders from P.O. 1488 through P.O. 1491-1400

KIT NUMBER

KIT DESCRIPTION

931,303,021


GIII Loading Label (922828 rev 2)

BEFORE WORKING ON VENDER: Remove power from vender by unplugging vender's main power cord from the AC voltage power source (wall outlet).

Reason for Fix:

The incorrect loading decal (923433-1.1) was installed on the following production runs 1488-A through 1491-1400. The correct loading decal should be 931,303,021.

	923433-1.1 <i>(incorrect decal)</i>	931,303,021 <i>(correct decal)</i>
Five packages have incorrect front retainer settings:	1. 20 oz Surge/Bolt	7
	2. 20 oz Powerade	9
	3. 16 oz Glass Fruitopia	10
	4. 16 oz Glass Straightwall	10
	5. 16 oz Can	9



ANY QUESTIONS??? CONTACT ROYAL VENDORS' CUSTOMER SERVICE DEPARTMENT
CALL TOLL FREE (800) 931-9214