



SERVICE BULLETIN # 00127

201 INDUSTRIAL BOULEVARD • KEARNEYSVILLE, WV 25430

Phone: (304) 728-7056 • Fax: (304) 725-6579 • Toll Free: (800) 931-9214

PAGE: 1 of 1

DATE: 6-19-02

REVISION: 04

SUBJECT: Merlin III Chip Replacement for Installation of a Coinco Model BA30B Validator

MODELS: Merlin III Venders with a 10.03 / 11.03 or Lower Control Board

KIT NUMBER	KIT DESCRIPTION
836067	Version 10.07 Control Chip (Merlin III)
836069	Version 11.06 Control Chip (Merlin III)



The following areas of this vender contain voltage, which can cause serious injury or even death. The main power cord, supplying 110 VAC to the evaporator, EMI filter, and refrigeration system. The power line from the EMI filter to the ballast and transformer. The ballast can produce upwards of 600 volts. Remove power from vender before working in any of these areas.

BEFORE WORKING ON VENDER: Remove power from vender by unplugging vender's main power cord from the AC voltage power source (wall outlet).

When installing a Coinco Validator, Model #BA30B, with a serial number 1795XXXXX (this is a data code for the 17th week of the year 1995) or higher, into a Merlin III vender with a 10.03 / 11.03 or lower control board, a revision 10.04 / 11.04 or higher chip must be installed to prevent any problems.

**ANY QUESTIONS??? CONTACT ROYAL VENDORS' CUSTOMER SERVICE DEPARTMENT
CALL TOLL FREE (800) 931-9214**