



# Helpful Hints 0032

*clear & easy*

426 INDUSTRIAL BOULEVARD • KEARNEYSVILLE WV 25430-2776 • USA  
Phone: +1 304 728-7056 • Fax: +1 304 725-6579 • Toll Free: 800 931-9214

PAGE: 1 of 1

DATE: 2-10-05

REVISION: 00

**SUBJECT:** Proper Depth Setting on Milk Venders

# of People  
Required



**MODELS:** Milk venders

**TOOLS REQUIRED:** None

**ESTIMATED TIME:** <1 minute

**REASON FOR HINT:** Proper depth setting on Milk venders is essential, especially for selections vending bottles from rear columns. When set incorrectly, the vend motors in rear columns may not turn far enough for the bottle to drop from the column, resulting in a hanging bottle and sold-out condition for those columns.

## PROCEDURE FOR CHANGING DEPTH SETTINGS:

1. Push the mode button on the vender's control board to access the Service Menu. Scroll to Selection Depth Setting Mode (SdEP). Press <enter>.
2. Scroll to the desired selection number to be changed. Press <enter>.
3. If "2" is flashing, use the <up> or <down> button to change the "2" to "1." Press <exit>.
4. Repeat this procedure for all bottle selections.

**ANY QUESTIONS???** CONTACT ROYAL VENDORS' CUSTOMER SERVICE DEPARTMENT  
**CALL TOLL FREE (800) 931-9214**