



SERVICE BULLETIN # 00038

201 INDUSTRIAL BOULEVARD • KEARNEYSVILLE, WV 25430

Phone: (304) 728-7056 • Fax: (304) 725-6579 • Toll Free: (800) 931-9214

PAGE: 1 of 1

DATE: 8-17-00

REVISION: 03

SUBJECT: Evaporator Frost

MODELS: Venders with Cold Control

KIT NUMBER

KIT DESCRIPTION

BEFORE WORKING ON VENDER: Remove power from vender by unplugging vender's main power cord from the AC voltage power source (wall outlet).

In the rare case where frost has accumulated on the evaporator, check the following in order:

1. Cold control is in normal position (screw slot vertical).
2. Vender spaced 4 inches from wall.
3. Condenser not blocked (debris under door or on condenser face).
4. Port door fit (make sure door swings freely).
5. Inner-door gasket seal (check for a good seal).

If the above items check out, then adjust temperature control by turning altitude adjustment screw, located in the bottom side of the thermostat, ¼ of a turn counter clockwise from the vertical position.

If this fails, then replace unit.

**ANY QUESTIONS??? CONTACT ROYAL VENDORS' CUSTOMER SERVICE DEPARTMENT
CALL TOLL FREE (800) 931-9214**