



Helpful Hints clear & easy

047

Page: 1 of 1

Date: 16 Jul 10

Revision: 02

426 Industrial Boulevard • Kearneysville WV 25430-2776 • USA
Telephone: +1 304 728 7056 • technicalinquiry@royalvendors.com
Toll-free in North America: 1 800 931 9214 • Fax: +1 304 725 4016
Canada: +1 905 738 5777 • Mexico: +52 55 5203 6887
Europe: +49 2158 95 1000 • Australia: +61 2 9890 5433

Number of
People
Required



SUBJECT: CCIV Interconnections

MODELS: CCIV


TOOLS REQUIRED: N/A

ESTIMATED TIME: N/A



The following areas of this vender contain voltage which can cause serious injury or even death: the main power cord, supplying 115-230 VAC to the evaporator, EMI filter, refrigeration system, monitor, and computer; the power line from the EMI filter to the ballast and transformer; and the ballast, which can produce upwards of 600 volts. Remove all power from the vender before working in any of these areas.

INFORMATION: This bulletin shows the harness / cable connections between the computer, monitor, and PayLink device. It also includes part numbers and color codes for the cables and harnesses. (Each cable or harness has a colored label wrapped around one end, except black.)



**ANY QUESTIONS? CONTACT ROYAL VENDORS' CUSTOMER SERVICE DEPARTMENT
IN NORTH AMERICA, CALL TOLL FREE 1 800 931 9214**