



# SERVICE BULLETIN # 00071

201 INDUSTRIAL BOULEVARD • KEARNEYSVILLE, WV 25430

Phone: (304) 728-7056 • Fax: (304) 725-6579 • Toll Free: (800) 931-9214

PAGE: 1 of 1

DATE: 6-19-02

REVISION: 03

**SUBJECT:** Replacement Chips for Version 5 Control Boards

**MODELS:** Merlin 2000

KIT NUMBER	KIT DESCRIPTION
836048	Version 5 Chip Kit

**BEFORE WORKING ON VENDER:** Remove power from vender by unplugging vender's main power cord from the AC voltage power source (wall outlet).

## INSTRUCTIONS:

Verification has been made that various revisions of the version 5 control boards for the Merlin 2000 Venders have been known to jackpot the coin mechanism in certain conditions or circumstances.

As a correction for this problem, we will be offering the revision 5.06 chip at no charge. These chips are available through your Royal Vendors' sales representative or distributor.



*The following areas of this vender contain voltage, which can cause serious injury or even death. The main power cord, supplying 110 VAC to the evaporator, EMI filter, and refrigeration system. The power line from the EMI filter to the ballast and transformer. The ballast can produce upwards of 600 volts. Remove power from vender before working in any of these areas.*

**ANY QUESTIONS??? CONTACT ROYAL VENDORS' CUSTOMER SERVICE DEPARTMENT  
CALL TOLL FREE (800) 931-9214**